



纺织和皮革类产品召回通报预警—2020年第01期

为了保障消费者的合法权益，欧盟、美国、加拿大和澳大利亚等国家建立了专门的预警通报机制，对不合格纺织和皮革类产品进行通报。CTT纺织和皮革类召回通报预警2020年第1期汇总了1月份有关的纺织和皮革类产品的通报信息。在该期间，欧盟、美国、加拿大和澳大利亚通报案例共15例，其中与中国有关的占3例。涉及的纺织和皮革产品是具有**伤害和绞勒风险**的儿童衬衫、童装套装、儿童上衣、儿童运动衫和背包盒，具有**窒息危害**的儿童上衣、婴儿连体衣和女童帽，以及**六价铬**超标的皮手套。

通报原因	违反法规/标准	通报数量	涉及产品
绞勒及伤害风险	EN 14682,CCPSA	9	儿童衬衫、童装套装、儿童上衣、儿童运动衫、背包盒
窒息危害	EN71	3	儿童上衣、婴儿连体衣、女童帽
六价铬	REACH	3	皮手套

部分典型案例如下：



产品：童装套装
 原产国：土耳其
 通告国：保加利亚
 风险描述：该产品的束带很长，颈部和腰部有自由端。这些束带可能会在儿童的各种活动中被困住，导致勒伤。
 采取措施：产品退出市场。



产品：儿童衬衫
 原产国：意大利
 通告国：保加利亚
 风险描述：罩衫颈部区域存在束带。绳索可能会在儿童的各种活动中被夹住并导致勒伤。
 采取措施：产品退出市场。



纺织和皮革类产品召回通报预警—2020年第01期



产品:	儿童上衣
原产国:	土耳其
通告国:	保加利亚
风险描述:	小卵石很容易脱落,产生小部件。小孩可能将小部件放在嘴里并有窒息危险。
采取措施:	产品退出市场。



产品:	女童帽
原产国:	中国
通告国:	加拿大
风险描述:	环扣可能会分离并对儿童造成窒息危险。
采取措施:	立即停止使用该产品,并与供应商联系以获取全额退款。



产品:	皮手套
原产国:	瑞士
通告国:	瑞典
风险描述:	皮革中发现的六价铬含量过高(测量值高达 5.8mg/kg)。六价铬可能会引起过敏反应。
采取措施:	从最终用户处召回产品。

参考网站:

- <https://www.cpsc.gov/Recalls/?Page=1>
- http://www.healthycanadians.gc.ca/recall-alert-rappel-avis/search-recherche/simple?s=&plain_text=&f_mc=4&js_en=&page=5&f_mc=4&f_sc=34
- http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/
- <https://www.productsafety.gov.au/recalls>

备注: 以上图片均来自以上参考网站。

中鼎检测技术有限公司

400-6789-666 <http://www.cttlab.com>

广东 (东莞、深圳、惠州、广州、中山)

电话:+86(0)769 8898 9888-884
邮箱:enquiry@cttlab.com

上海

电话:+86 186 7621 9748
邮箱:ricky.fang@cttlab.com

香港

电话:+852 3960 7181
邮箱:hk@cttlab.com

浙江 (义乌、宁波)

电话:+86(0)579 8998 6543-800
邮箱:zj@cttlab.com

美国

电话:+1-562 470 7217
邮箱:usa@cttlab.com

福建 (泉州、厦门)

电话:+86(0)595 68099099-652
邮箱:fj@cttlab.com

奥地利

电话:+43 699 1000 3888
邮箱:eu@cttlab.com



Textile & Leather Products Recall Notifications-2020 report 01

EU, USA, Canada and Australia have established rapid alert systems to facilitate the rapid exchange of information and measures taken to prevent or restrict the marketing or use of products posing a serious risk to the health and safety of consumers. Notification in 2020 report 01 on Textile & Leather products is presented in the following table. There were total 15 notifications in January with 3 **notifications from China**. Notifications of products mainly involve Children's shirt, Children's clothing set, Children's blouse, Children's sweatshirt, Backpack boxes with **injuries and strangulation**, Children's blouse, Baby's bodysuit, Girls' Hat with **choking hazard**, Leather gloves containing excessive **Cr (VI)**.

Risk	Regulation / Standard	Notification count	Products
Injuries and strangulations risk	EN 14682,CCPSA	9	Children's shirt, Children's clothing set, Children's blouse, Children's sweatshirt, Backpack boxes
Choking hazard	EN 71	3	Children's blouse, Baby's bodysuit, Girls' Hat
Cr (VI)	REACH	3	Leather gloves

Some typical cases are as follow:



Product :	Children's clothing set
Country of origin:	Turkey
Alert submitted by:	Bulgaria
Risk type:	The product has long drawstrings with free ends at the neck and waist area. These drawstrings can become trapped during various activities of a child, leading to strangulation or injuries.
Measures ordered:	Withdrawal of the product from the market.



Product :	Children's shirt
Country of origin:	Italy
Alert submitted by:	Bulgaria
Risk type:	There are drawstring in the neck area of the of the blouse hood. The cords could become trapped during various activities of a child and lead to strangulation.
Measures ordered:	Withdrawal of the product from the market.



Textile & Leather Products Recall Notifications-2020 report 01



Product :	Children`s blouse
Country of origin:	Turkey
Alert submitted by:	Bulgaria
Risk type:	Pebbles can be easily detached, generating small parts. A small child can put the small part in the mouth and choke on it.
Measures ordered:	Withdrawal of the product from the market.



Product :	Girls' Hat
Country of origin:	China
Alert submitted by:	Canada
Risk type:	The loop fastener may detach and pose a choking hazard to children.
Measures ordered:	Immediately stop using the product and contact suppliers for a full refund.



Product :	Leather gloves
Country of origin:	Switzerland
Alert submitted by:	Sweden
Risk type:	The amount of chromium (VI) found in the leather is too high (measured value up to 5.8 mg/kg).
Measures ordered:	Recall of the product from end users.

Referenced Websites:

- <https://www.cpsc.gov/Recalls/?Page=1>
- http://www.healthycanadians.gc.ca/recall-alert-rappel-avis/search-recherche/simple?s=&plain_text=&f_mc=4&js_en=&page=5&f_mc=4&f_sc=34
- http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/
- <https://www.productsafety.gov.au/recalls>

Remark: All pictures above are selected from the referenced websites.

Consumer Testing Technology Co., Ltd.

<http://www.cttlab.com>

Guangdong
(Dongguan / Shenzhen / Huizhou / Guangzhou / Zhongshan)
Tel:+86(0)769 8898 9888-884
E-mail:enquiry@cttlab.com

Zhejiang
(Yiwu / Ningbo)
Tel:+86(0)579 8998 6543-800
E-mail:zj@cttlab.com

Fujian
(Quanzhou/Xiamen)
Tel: +86(0)595 68099099-652
E-mail:fj@cttlab.com

Shanghai
Tel:+86 186 7621 9748
E-mail:ricky.fang@cttlab.com

Hongkong
Tel:+852 3960 7181
E-mail:hk@cttlab.com

USA
Tel: +1- 562 470 7217
E-mail:usa@cttlab.com

Austria
Tel: +43 699 1000 3888
E-mail:eu@cttlab.com