
















In order to protect consumer legitimate rights, the European Union, UK, USA, Canada, Australia together with other countries in the world has established special notification systems to provide information of products which may cause risk to people health and safety.

A total of 60 notifications of children's toys were declared in EU RAPEX are from Cyprus, Spain, Germany, France, Poland, Czechia, Lithuania, Malta, Croatia, Hungary, Sweden, ; 10 notifications in UK official for product safety and Standards website; 0 notification in Healthy Canadians official website; 3 notifications in Australian product safety recalls official website; 0 notification in CPSC official website from 40 to 43 week of 2024. Up to 67 notifications of children's toys are from China among all those notifications. Toys were notified because: Contain or release small parts, The migration of boron from the product is too high, Phthalates content exceeds the limit level, etc.



Consumer Testing Technology Co., Ltd.

(2) 400-6789-666 http://www.cttlab.com

Fujian: +86(0)595-6809 9099

U.S.A: +1 562 470 7215

Guangdong: +86(0)769-8898 9888-884

Hong Kong: +852 9319 8131 Vietnam: +84 024 3928 8688 **Zhejiang**: +86(0)579-8998 6543


Taiwan: +886-0905-989-569

Austria: +43 699 1000 3888









Consumer Testing Technology Co., Ltd.

Hong Kong: +852 9319 8131

2 400-6789-666 http://www.cttlab.com

Fujian: +86(0)595-6809 9099

U.S.A: +1 562 470 7215

Guangdong: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543

Taiwan: +886-0905-989-569

















CTT-TT-S24010E

Toy Products Recall Notifications-2024 report 10

Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Choking Contain or release small parts.	Cyprus Finland Lithuania Romania Germany Austria France UK	EN 71-1 Toys (Safety) Regulations 2011	23	Plastic toy Soft toy Toy rattle Fishing toy Plastic toy Bath toys Push along toy Toy pistol set Toy telephone Toy airplane Baby book Toy doll on tricycle Keyring with soft toy Pencil case Toy gun set Plastic Toy Gift Set	
Chemical The migration of boron from the product is too high.	Germany France Lithuania Estonia UK	EN 71-3 Toys (Safety) Regulations 2011	10	Toy slime Super Clay	
Chemical Phthalates content exceeds the limit level.	Poland Lithuania Cyprus UK	REACH ANNEX XVII Toys (Safety) Regulations 2011	8	Inflatable toy Plastic doll Plastic ball Bath toy set Beach ball Halloween Accessory	A A A A A A A A A A A A A A A A A A A

Consumer Testing Technology Co., Ltd.

1 400-6789-666 http://www.cttlab.com

U.S.A: +1 562 470 7215

Guangdong: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543 Fujian: +86(0)595-6809 9099

Hong Kong: +852 9319 8131 **Taiwan**: +886-0905-989-569 Vietnam: +84 024 3928 8688 Austria: +43 699 1000 3888



















Continue:

Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Injuries The product contains magnets with a high magnetic flux.	Slovenia UK	EN 71-1 Toys (Safety) Regulations 2011	6	Magnetic toy Fishing toy set Doll Magnetic Darts Toy	MAGNETIC STICKS 3:
Choking The seams come easily apart, making the filling accessible.	Finland Poland	EN 71-1	3	Baby gym play mat Soft toy	
Burns The product may short-circuit or overheat, posing a fire risk.	UK	Toys (Safety) Regulations 2011	2	Halloween Projector Torch Battery Powered Ride On Toy	
Injuries The diameter of wheels and handlebar grips are inadequate. The steering tubes are not resistant to load and may collapse during a ride. A child may fall off the scooter and suffer injuries.	Poland	EN 71-1	1	Toy scooter	

Zhejiang: +86(0)579-8998 6543

Consumer Testing Technology Co., Ltd.

2 400-6789-666 http://www.cttlab.com

Guangdong: +86(0)769-8898 9888-884

Hong Kong: +852 9319 8131 **Taiwan**: +886-0905-989-569

Vietnam: +84 024 3928 8688 Austria: +43 699 1000 3888



Fujian: +86(0)595-6809 9099 **U.S.A**: +1 562 470 7215

















Continue:

Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Injuries The product has accessible openings and holes, in which children can become trapped and suffer injuries. The swing seat is attached to the rope by knots, which can easily loosen and cause a child to fall off the swing.	Poland	EN 71-8	1	Swing	
Choking Contain or release small parts.The seams come easily apart, making the filling accessible.	Germany	EN 71-1	1	Soft toy	
Choking Contain or release small parts. Due to their characteristic appearance, form, colour and size, the product may be mistaken for foodstuff.	Romania	EN 71-1	1	Toy jewellery set	
Damage to sight The material of the projectile is too hard and can cause eye injuries.	Australia	Mandatory standard for projectile toys	1	Toy bow and arrow set	

Consumer Testing Technology Co., Ltd.

1 400-6789-666 http://www.cttlab.com

U.S.A: +1 562 470 7215

Fujian: +86(0)595-6809 9099 **Guangdong**: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543

Hong Kong: +852 9319 8131 **Taiwan**: +886-0905-989-569 Vietnam: +84 024 3928 8688 Austria: +43 699 1000 3888

















CTT-TT-S24010E

Toy Products Recall Notifications-2024 report 10

Continue:

Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Choking There is a risk of serious injury or death from choking if beads are inhaled.	Australia	The permanent ban on toys that inflate and contain beads	1	balloons	
Choking The product is not safe if us ed for infant sleep and/or if bedding material is added when in use as the head res t and body support insert c an increase the risk of suffo cation.	Australia	/	1	Cradle 'n Swing	
Environment Lead content exceeds the limit level.	Sweden	RoHS 2 Directive	1	Toy snail	100 (g) (100 (g) (100 (g)
Environment Lead and Cadmium content exceeds the limit level.	Sweden	RoHS 2 Directive	1	Battery-operated toy	

Consumer Testing Technology Co., Ltd.

2 400-6789-666 http://www.cttlab.com

U.S.A: +1 562 470 7215

Fujian: +86(0)595-6809 9099 **Guangdong**: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543

Hong Kong: +852 9319 8131 **Taiwan**: +886-0905-989-569 Vietnam: +84 024 3928 8688





















Continue:

Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Chemical Environment SCCPs and Lead content exceeds the limit level.	Sweden	RoHS 2 Directive POPs Regulation	1	Toy helicopter	
Chemical Environment Phthalates, SCCPs and Lead content exceeds the limit level.	Sweden	RoHS 2 Directive POPs Regulation	1	Toy robot	TOBOUT MANAGEMENT
Injuries Suffocation The diameter of the front wheels of the scooter is too small, When a child rides a scooter on an uneven surface, the wheel can get stuck in a pit and the child may fall, suffering injuries.Plastic film is not breathable, if a child plays with the packaging, the plastic can cover the mouth and nose, causing the child to suffocate.	Poland	EN 71-1	1	Toy scooter	
Chemical Choking Contain or release small parts. The button batteries inside the sound producing part can also detach at the same time. A child could put them in the mouth, which could cause damage to the child's gastrointestinal tract or choking.	Finland	EN 71-1 EN 62115	1	Toy dinosaur	24-0318-02 13 White the state of the state

Consumer Testing Technology Co., Ltd.

2 400-6789-666 http://www.cttlab.com

U.S.A: +1 562 470 7215

Fujian: +86(0)595-6809 9099 **Guangdong**: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543

Hong Kong: +852 9319 8131 **Taiwan**: +886-0905-989-569

Vietnam: +84 024 3928 8688 Austria: +43 699 1000 3888

















Risk	Notifying country	Regulation/ Standard	Notifica- tion count	Products	Partial Pictures
Burns Chemical					
Strangulation					
The brown textile lead has a					
slipknot. Children can easily					
wrap it around their necks					
and strangle themselves.					THE LOT AND
Additionally, the batteries can	France	EN 71-1	1	Plastic toy	
overheat and cause burns if	Traffice	LIV/I	'	r tastic toy	(A)
the toy is blocked.The					() ()
batteries are easily					
accessible. A chemical hazard					
could arise if they were to be					
damaged and placed in the					
mouth.					
Burns Chemical Choking,					
Damage to sight					
Contain or release small					
parts.In addition, the toy					1405
material contains MI and	France	Toy Safety Directive	1	Ball	
MCI. MCI and MI cause severe	France	EN 71-1	,	Batt	004
skin burns and eye damage					
(if in contact with the eyes),					
and may cause an allergic					
skin reaction.					

Referenced web:

- https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true
- https://www.cpsc.gov/Recalls
- https://recalls-rappels.canada.ca/en/search/site
- https://www.productsafety.gov.au/recalls
- https://www.gov.uk/product-safety-alerts-reports-recalls?

Remark: All pictures above are selected from the referenced web.

Consumer Testing Technology Co., Ltd.

2 400-6789-666 http://www.cttlab.com

U.S.A: +1 562 470 7215

Guangdong: +86(0)769-8898 9888-884 **Zhejiang**: +86(0)579-8998 6543 **Fujian**: +86(0)595-6809 9099

 Hong Kong: +852 9319 8131
 Taiwan: +886-0905-989-569

 Vietnam: +84 024 3928 8688
 Austria: +43 699 1000 3888














玩具产品召回通报预警-2024年第10期

为了保障消费者的合法权益,欧盟、英国、美国、加拿大、澳大利亚等国均建立了专门的预警通报机制,对不合格的玩具产品进行通报。

2024年第40-43周,欧盟RAPEX通报公布的玩具通报案例共60例,来自 奥地利、塞浦路斯、爱沙尼亚、芬兰、法国、德国、立陶宛、波兰、罗马尼亚、斯洛文尼亚、瑞典;英国产品安全与标准部门官网10例,加拿大卫生部官网0例,澳大利亚产品安全召回官网3例,美国CPSC官网0例。所有的通报案例当中原产国是中国的案例高达67例,涉及的通报原因包括含有或易产生小部件,产品的硼迁移量过高,邻苯二甲酸酯含量超标等。



中鼎检测技术有限公司

2 400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131 越南 TEL: +84 024 3928 8688 浙江 TEL: +86(0)579-8998 6543

奥地利 TEL: +43 699 1000 3888

台湾 TEL: +886-0905-989-569

福建 TEL: +86(0)595-6809 9099 美国 TEL: +1 562 470 7215















玩具产品召回通报预警-2024年第10期



中鼎检测技术有限公司

2 400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884 香港 TEL: +852 9319 8131

越南 TEL: +84 024 3928 8688

浙江 TEL: +86(0)579-8998 6543

台湾 TEL: +886-0905-989-569 奥地利 TEL: +43 699 1000 3888 福建 TEL: +86(0)595-6809 9099















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
窒息 含有或易产生小部件。	塞 立 罗 奥 法 英	EN 71-1 Toys (Safety) Regulations 2011	23	塑软玩的塑沐推玩玩玩宝车玩文玩玩玩玩玩玩玩玩玩玩玩宝车玩文玩玩具具具宝的的的盒 枪品具具 具人 人 机 书具起来 我 我 我 我 我 我 我 我 我 我 我 我 我 我 我 我 是	
化学 产品的硼迁移量过高。	德国 法国 立陶宛 爱沙尼亚 英国	EN 71-3 Toys (Safety) Regulations 2011	10	玩具的粘液 超级粘土	
化学 邻苯二甲酸酯含量超标。	波兰 立陶宛 塞浦路斯 英国	REACH ANNEX XVII Toys (Safety) Regulations 2011	8	充气玩具 塑料娃娃 塑料球 沐浴玩具套装 沙滩球 万圣节的配件	A. A.

续:

中鼎检测技术有限公司

400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131

越南 TEL: +84 024 3928 8688

浙江 TEL: +86(0)579-8998 6543

台湾 TEL: +886-0905-989-569 **奥地利** TEL: +43 699 1000 3888 福建 TEL: +86(0)595-6809 9099















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
伤害 产品含小型高能磁铁。	斯洛文尼亚 英国	EN 71-1 Toys (Safety) Regulations 2011	6	磁性玩具 钓鱼玩具套装 娃娃 磁性飞镖玩具	MAGNETIC U C. STICKS 31:
窒息 玩具接缝容易裂开,导致填 充物可触。	芬兰波兰	EN 71-1	3	婴儿健身游戏垫 软体玩具	
烧伤 产品可能短路或者过热,存 在火灾风险。	英国	Toys (Safety) Regulations 2011	2	万圣节投影仪火炬 电池驱动的玩具	
伤害 车轮和车把把手的直径不足。转向管不耐负载,可能在行驶过程中崩溃。儿童可能从滑板车上摔下来受伤。	波兰	EN 71-1	1	玩具滑板车	

续:

中鼎检测技术有限公司

400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131 越南 TEL: +84 024 3928 8688 **浙江** TEL: +86(0)579-8998 6543

台湾 TEL: +886-0905-989-569 **奥地利** TEL: +43 699 1000 3888 福建 TEL: +86(0)595-6809 9099















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
伤害 产品有可接近的开口和洞, 儿童可能会被困在里面并受 伤。秋千座与绳子系有结, 很容易松开,导致孩子从秋 千上掉下来。	波兰	EN 71-8	1	秋千	
窒息 产品含有小部件,玩具接缝 容易裂开,导致填充物可窒 息。	德国	EN 71-1	1	软体玩具	
窒息 产品含有小部件,由于其独 特的外观、形状、颜色和大 小,该产品可能被误认为是 食品。	罗马尼亚	EN 71-1	1	玩具饰品套装	
视力损伤 弹丸的材料太硬,可能会造 成眼睛受伤。	澳大利亚	The Consumer Goods (Projectile Toys) Safety Standard 2020	1	玩具弓箭套装	

续:

中鼎检测技术有限公司

400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131 越南 TEL: +84 024 3928 8688 **浙江** TEL: +86(0)579-8998 6543

台湾 TEL: +886-0905-989-569 **奥地利** TEL: +43 699 1000 3888 福建 TEL: +86(0)595-6809 9099















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
窒息 如果吸入气球中的珠子,则 有因窒息而造成严重伤害或 死亡的风险。	選大利 1/1	The permanent ban on toys that inflate and contain beads	1	气球	
窒息 商品用于婴儿睡眠是不安全的,且/或若在使用时添加床上用品作为头枕和身体支撑物,会增加窒息的风险。	澳大利亚	/	1	摇篮秋千	
环境 铅含量超标。	瑞典	RoHS 2 Directive	1	玩具蜗牛	900 (d. 1) (d. 1
环境 铅和镉含量超标。	瑞典	RoHS 2 Directive	1	电池驱动玩具	

续:

中鼎检测技术有限公司

400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131

越南 TEL: +84 024 3928 8688

浙江 TEL: +86(0)579-8998 6543 台湾 TEL: +886-0905-989-569

奥地利 TEL: +43 699 1000 3888

福建 TEL: +86(0)595-6809 9099 美国 TEL: +1 562 470 7215















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
化学 环境 SCCPs和铅含量超标。	瑞典	RoHS 2 Directive POPs Regulation	1	玩具直升机	
化学 环境 邻苯二甲酸酯、SCCPs和铅 含量超标。	瑞典	RoHS 2 Directive POPs Regulation	1	玩具机器人	
传書室息 滑板车的前轮直径太小,当孩子在不平整的路面上骑滑板车时,轮子可能会卡在坑里,孩子可能会摔倒受伤。塑料薄膜是不透气的,如果孩子玩弄包装,塑料可能会覆盖嘴和鼻子,造成孩子窒息。	波兰	EN 71-1	1	玩具滑板车	
化学 窒息 含有或易产生小部件。发声部件内部的纽扣电池也可以同时拆卸。孩子可能会把它们放进嘴里,这可能会损害孩子的胃肠道或导致窒息。	芬兰	EN 71-1 EN 62115	1	玩具恐龙	Records 62 as the second of th

续:

中鼎检测技术有限公司

400-6789-666 http://www.cttlab.com

广东 TEL: +86(0)769-8898 9888-884

香港 TEL: +852 9319 8131 越南 TEL: +84 024 3928 8688 **浙江** TEL: +86(0)579-8998 6543

台湾 TEL: +886-0905-989-569 **奥地利** TEL: +43 699 1000 3888 福建 TEL: +86(0)595-6809 9099

















玩具产品召回通报预警-2024年第10期

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
烧伤 化学 勒伤 棕色的纺织领结有一个活结。孩子们很容易把它缠在脖子上造成勒伤风险。此外,如果玩具被堵塞,电池会过热并导致烧伤。电池很容易拿到。如果它们被损坏并放入口中,可能会产生化学危害。	法国	EN 71-1	1	塑料玩具	
烧伤 化学 窒息 视力损害 玩具含有小零件,可以很容 易地拆开。此外,玩具材料 中含有甲基异噻唑啉酮 (MI)和甲基氯异噻唑啉酮 (MCI),可能会导致严重的 皮肤烧伤和眼部损伤(如果 与眼睛接触),并可能引起 皮肤过敏反应。	法国	Toy Safety Directive EN 71-1	1	球	2555

参考网站:

- https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true
- https://www.cpsc.gov/Recalls
- https://recalls-rappels.canada.ca/en/search/site
- https://www.productsafety.gov.au/recalls
- https://www.gov.uk/product-safety-alerts-reports-recalls?

备注:以上图片均来自以上参考网站。

中鼎检测技术有限公司

2 400-6789-666 http://www.cttlab.com

福建 TEL: +86(0)595-6809 9099

美国 TEL: +1 562 470 7215

广东 TEL: +86(0)769-8898 9888-884

浙江 TEL: +86(0)579-8998 6543

越南 TEL: +84 024 3928 8688 奥地利 TEL: +43 699 1000 3888

