



Textile & Leather & Shoes & Bag Products Recall Notifications - 2025 report 1

In order to protect the legitimate rights and interests of consumers, countries such as the European Union, the United States, Canada and Australia have established special early warning and notification mechanisms to notify substandard products. CTT summarizes the notification information related to textile & leather & shoes & bag products in the first quarter of 2025. During this period, the European Union announced 35 notified cases, the United States announced 10 notified cases, Canada announced 9 notified cases, and Australia announced 4 notified cases, for a total of 58 cases. Among the countries of origin involved, including China, Turkey, Portugal, Peru, Vietnam, The Netherlands and so on, among which 31 cases were related to China, accounting for 53%; The types of risks involved in the recalled products include: rope straps cause injury and strangulation hazard, burn hazard, chemical hazard, small parts choking hazard, etc. More details are as follows:

EU RAPEX:

Risk	Regulation / Standard	Notification count	Products
Chemical hazard	REACH POPs	20	Children's sandals: Phthalene(DBP、DEHP、DINP)、Lead、Cadmium Children's slippers: Phthalene(DBP、DEHP、DINP)、Lead Children's wellington boots、Children's rain boots: Phthalene(DBP、DEHP)、SCCPs Plastic sandals: Phthalene(DEHP)、Cadmium Women's hooded jacket: PFAS(PFOA) Mattress protector: PFAS(N-EtFOSE) Gloves: Chromium(VI) Bicycle gloves、Poncho、Cosmetic bag、Shower cap: Phthalene(DEHP) Flip flops: Phthalene(DEHP、DIBP、DBP) Water shoes、Children's flip flops: Phthalene(DEHP、DBP) Shoulder bag: Nickel release Children's hand bag: Phthalene(DEHP、DIBP、DBP)、Cadmium、SCCPs Rain boots: Phthalene(DBP)
Rope straps cause injury and strangulation hazard	GPSD GPSR EN 14682	10	Children's clothing set; Children's sweatshirt; Children's skirt; Children's trousers; Children's bikini; Children's dress; Children's coat; Nappy cover
Small parts choking hazard	GPSD GPSR	4	Children's sandals; Baby's sleepsuits, pyjamas and hooded towels; Children's shoes; Nappy cover
Injury hazard	GPSR	1	Socks
Cuts hazard	GPSR	1	Children's earmuffs (The product has a sharp point)

United States CPSC:

Risk	Regulation / Standard	Notification count	Products
Burn hazard	16 CFR 1615/1616 16 CFR 1610	9	Children's bathrobe; Children's nightgowns, pajama sets and robes; Children's pajamas; Children's pajama sets and robes; Children's pajama sets; Girls pajama sets; Children's holiday pajama sets; Children's pajamas and nightgowns; Women's sweatshirts and women's and men's hoodies
Rope straps cause injury and strangulation hazard	16 CFR 1120	1	Youth jackets

Canada HC:

Risk	Regulation / Standard	Notification count	Products
Burn hazard	SOR/2016-169 SOR/2016-194	7	Children's pajamas and nightgowns; Children's holiday pajama sets; Children's nightgowns, pajama sets and robes; Children's bathrobes; Children's pajama sets; Hoodies and half-zip sweatshirts
Microbial hazard	CCPSA	1	Toaster and toaster bunting suits
Injury hazard	CCPSA	1	Safety boots (The protection information on the label is inaccurate)

Consumer Testing Technology Co., Ltd.

E-mail: enquiry@cttllab.com <http://www.cttllab.co>

Guangdong

Shenzhen/Shenzhen/Huizhou/Guangzhou/Zhongshan)

L: +86(0)769-8898 9888-884

Zhejiang

(Yiwu/Ningbo)

TEL: 0579-8998 6543

Fujian

(Quanzhou/Xiamen)

TEL: 0595-6809 9099

Hong Kong

TEL: +852 9319 813

Hanoi, Vietnam

L: +84 024 3928 8688

mail: vn@cttllab.com

Linz, Austria

TEL: +43 670 1928192

E-mail: eu@cttllab.com

Vancouver, Canada

TEL: +1 778 288 5623

E-mail: north.america@cttllab.com



Scan with WeChat for mc information.

V 2025.04


Australia ACCC:

Risk	Regulation / Standard	Notification count	Products
Burn hazard	Consumer Goods (Children's Nightwear and Limited Daywear and Paper Patterns for Children's Nightwear) Safety Standard 2017	1	Children's pyjama sets
Choking/Internal burn hazard	Button and coin batteries mandatory standards	2	LED baseball cap (The button batteries of the product are easily accessible to young children); Cap with light-up peak (The button batteries of the product are easily accessible to young children)
Skin irritation and allergic reaction hazard	ACCC	1	Nursing pillow

Some typical cases are as follows:


Product:	Women's hooded jacket
Country of origin:	United Kingdom
Alert submitted by:	Belgium
Risk description:	The product contains an excessive amount of Perfluorooctanic acid (PFOA) (measured value: 34µg/kg). This substance is carcinogenic and poses a risk to the environment.
Regulation/Standard:	POPs



Product:	Plastic sandals
Country of origin:	China
Alert submitted by:	Malta
Risk description:	The plastic material of the sandals has an excessive concentration of bis(2-ethylhexyl) phthalate (DEHP) (measured value up to 21.7%) and cadmium (measured values up to 1.2 mg/kg). DEHP may harm the health by causing possible damage to the reproductive system. Cadmium is harmful to human health because it accumulates in the body, can damage the kidneys and bones and it may cause cancer.
Regulation/Standard:	REACH



Product:	Children's pajama sets
Country of origin:	China
Alert submitted by:	United States, Canada
Risk description:	The recalled children's pajamas violate the 16 CFR 1615/1616 federal flammability regulations for children's sleepwear, posing a risk of burn injuries to children. The recalled children's pajamas violate the SOR/2016-169 flammability requirements for children's sleepwear, posing a risk of burn injuries to children.
Regulation/Standard:	16 CFR 1615/1616, SOR/2016-169

Consumer Testing Technology Co., Ltd.

E-mail: enquiry@cttlab.com <http://www.cttlab.co>
Guangdong

(Guangzhou/Shenzhen/Huizhou/Guangzhou/Zhongshan)

L: +86(0)769-8898 9888-884

Zhejiang

(Yiwu/Ningbo)

TEL: 0579-8998 6543

Fujian

(Quanzhou/Xiamen)

TEL: 0595-6809 9099

Hong Kong

TEL: +852 9319 813

Hanoi, Vietnam

L: +84 024 3928 8688

 mail: vn@cttlab.com
Linz, Austria

TEL: +43 670 1928192

 E-mail: eu@cttlab.com
Vancouver, Canada

TEL: +1 778 288 5623

 E-mail: north.america@cttlab.com


Scan with WeChat for mc information.

V 2025.04



Product:	Nappy cover
Country of origin:	Portugal
Alert submitted by:	Spain
Risk description:	The product has small parts (buttons) that can be easily detached. A small child may put them in the mouth and choke. Moreover, the nappy cover has decorative bows around the waist with loose cords. The cords with free ends in the waist area are too long. The cords can become trapped during various activities of a child, leading to injuries.
Regulation/Standard:	GPSR、EN 14682



Product:	Youth jackets
Country of origin:	China
Alert submitted by:	United States
Risk description:	The drawstring in the hood of the recalled jackets can get caught on objects and cause death or serious injury to children due to the strangulation hazard. The jackets are in violation of the 16 CFR 1120 federal regulations for children's upper outerwear and present a substantial product hazard.
Regulation/Standard:	16 CFR 1120



Product:	Shoulder bag
Country of origin:	Italy
Alert submitted by:	France
Risk description:	The rate of nickel release is too high (measured value: 19 µg/cm2/week). Nickel is a strong sensitizer and causes allergic reactions if present in articles that come into direct and prolonged contact with the skin.
Regulation/Standard:	REACH



Product:	Children's trousers
Country of origin:	Turkey
Alert submitted by:	Belgium
Risk description:	The product has long functional cords with free ends in the waist area. These cords can become trapped during various activities of a child, leading to injuries.
Regulation/Standard:	GPSR、EN 14682



Product:	Children's shoes
Country of origin:	China
Alert submitted by:	France
Risk description:	The tassel and the textile/rhinestone element of the tassel can easily detach. A small child may put them in the mouth and choke.
Regulation/Standard:	GPSD

Consumer Testing Technology Co., Ltd.

 E-mail: enquiry@cttlab.com <http://www.cttlab.co>
Guangdong

(Guangzhou/Shenzhen/Huizhou/Guangzhou/Zhongshan)

L: +86(0)769-8898 9888-884

Zhejiang

(Yiwu/Ningbo)

TEL: 0579-8998 6543

Fujian

(Quanzhou/Xiamen)

TEL: 0595-6809 9099

Hong Kong

TEL: +852 9319 813

Hanoi, Vietnam

L: +84 024 3928 8688

 mail: vn@cttlab.com
Linz, Austria

TEL: +43 670 1928192

 E-mail: eu@cttlab.com
Vancouver, Canada

TEL: +1 778 288 5623

 E-mail: north.america@cttlab.com


Scan with WeChat for more information.

V 2025.04



Product:	Nursing pillow
Country of origin:	China
Alert submitted by:	Australia
Risk description:	Polyester filaments may escape from the outer casing of the pillow. Risk of skin irritation and allergic reaction from the polyester filaments.
Regulation/Standard:	ACCC



Product:	Socks
Country of origin:	Turkey
Alert submitted by:	Ireland
Risk description:	The inside toe area of the sock is made with an uncut loop. The uncut loop in the product may lead to tightness in the toe area, restricting blood circulation which can result in injuries.
Regulation/Standard:	ACCC



Product:	Toaster and toaster bunting suits
Country of origin:	Vietnam
Alert submitted by:	Canada
Risk description:	A small number of the recalled products were found to contain mould. Mould may pose a health risk to individuals with compromised immune systems, damaged lungs or an allergy to mould.
Regulation/Standard:	CCPSA



Product:	Women's sweatshirts and women's and men's hoodies
Country of origin:	Peru
Alert submitted by:	United States
Risk description:	The recalled sweatshirts and hoodies violate the 16 CFR 1610 federal flammability standard for clothing, posing a burn hazard to consumers.
Regulation/Standard:	CCPSA

Different markets have different requirements for textiles & leather & shoes & bag products. Therefore, it is particularly important to understand the requirements of export markets for products, especially for children's products, and to design and produce in strict accordance with relevant regulations and standards. Avoid the risk of recalls or claims due to product quality issues.

Referenced web:
<https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>
<https://www.cpsc.gov/Recalls>
<https://recalls-rappels.canada.ca/en/search/site>
<https://www.productsafety.gov.au/recalls>
 Remark: All pictures above are selected from the referenced web.

Consumer Testing Technology Co., Ltd.

E-mail: enquiry@cttlab.com <http://www.cttlab.co>

Guangdong
 (Guangzhou/Shenzhen/Huizhou/Guangzhou/Zhongshan)
 L: +86(0)769-8898 9888-884

Zhejiang
 (Yiwu/Ningbo)
 TEL: 0579-8998 6543

Fujian
 (Quanzhou/Xiamen)
 TEL: 0595-6809 9099

Hong Kong
 TEL: +852 9319 813

Hanoi, Vietnam
 L: +84 024 3928 8688
 mail: vn@cttlab.com

Linz, Austria
 TEL: +43 670 1928192
 E-mail: eu@cttlab.com

Vancouver, Canada
 TEL: +1 778 288 5623
 E-mail: north.america@cttlab.com





纺织和皮革鞋包类产品召回通报预警—2025年第1期

为了保障消费者的合法权益，欧盟、美国、加拿大和澳大利亚等国家建立了专门的预警通报机制，对不合格产品进行通报。CTT汇总了2025年第一季度纺织和皮革鞋包类产品的通报信息。在该期间，欧盟公布通报案例35例，美国公布通报案例10例，加拿大公布通报案例9例，澳大利亚公布通报案例4例，共58例。所涉及的原产国，包括中国、土耳其、葡萄牙、秘鲁、越南和荷兰等，其中与中国相关的有31例，占53%；所涉及的召回产品风险类型，包括：绳带引起受伤和绞勒危害、烧伤危害、有害化学物质超标危害、小部件窒息危害等。更多详情如下：

欧盟 RAPEX:

风险类型	违反法规/标准	通报数量	涉及产品大类
有害化学物质超标危害	REACH POPs	20	儿童凉鞋：邻苯（DBP、DEHP、DINP）、铅、镉 儿童拖鞋：邻苯（DBP、DEHP、DINP）、铅 儿童威灵顿靴、儿童雨靴：邻苯（DBP、DEHP）、短链氯化石蜡 塑料凉鞋：邻苯（DEHP）、镉 女式连帽夹克：PFAS(PFOA) 床垫保护套：PFAS(N-EtFOSE) 手套：六价铬 自行车手套、雨披、化妆包、浴帽：邻苯（DEHP） 人字拖：邻苯（DEHP、DIBP、DBP） 水鞋、儿童人字拖：邻苯（DEHP、DBP） 肩包：镍释放 儿童手提包：邻苯（DEHP、DIBP、DBP）、镉、短链氯化石蜡 雨靴：邻苯（DBP）
绳带引起受伤和绞勒危害	GPSD GPSR EN 14682	10	童装套装；儿童运动衫；儿童半身裙；儿童长裤；儿童比基尼；儿童连衣裙；儿童外套；尿布套
小部件窒息危害	GPSD GPSR	4	儿童凉鞋；婴儿一件套睡衣、睡衣裤和连帽毛巾；童鞋；尿布套
受伤危害	GPSR	1	袜子
刺/割伤危害	GPSR	1	儿童耳罩（产品有尖点）

美国 CPSC:

风险类型	违反法规/标准	通报数量	涉及产品大类
烧伤危害	16 CFR 1615/1616 16 CFR 1610	9	儿童浴袍；儿童睡裙、睡衣裤套装和长袍；儿童睡衣裤；儿童睡衣裤套装和长袍；儿童睡衣裤套装；女童睡衣裤套装；儿童假日睡衣裤套装；儿童睡衣裤和睡裙；女式运动衫和男女款连帽衫
绳带引起受伤和绞勒危害	16 CFR 1120	1	青年夹克

加拿大 HC:

风险类型	违反法规/标准	通报数量	涉及产品大类
烧伤危害	SOR/2016-169 SOR/2016-194	7	儿童睡衣裤和睡裙；儿童假日睡衣裤套装；儿童睡裙、睡衣裤套装和长袍；儿童浴袍；儿童睡衣裤套装；连帽衫和半拉链运动衫
微生物危害	CCPSA	1	冬季室外玩耍保暖防水服

中鼎检测技术有限公司

E-mail: enquiry@cttlab.com <http://www.cttlab.com>

广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)

TEL: 0579-8998 6543

福建 (泉州、厦门)

TEL: 0595-6809 9099

香港

TEL: +852 9319 8131

越南 河内

TEL: +84 024 3928 8688

E-mail: vn@cttlab.com

奥地利 林茨

TEL: +43 670 1928192

E-mail: eu@cttlab.com

加拿大 温哥华

TEL: +1 778 288 5623

E-mail: north.america@cttlab.com



扫描左侧二维码，
关注“CTT 中鼎检测”
Scan QR code for
more information
V 2025.04



受伤危害	CCPSA	1	安全靴（标签上保护信息不准确）
------	-------	---	-----------------

澳大利亚 ACCC:

风险类型	违反法规/标准	通报数量	涉及产品大类
烧伤危害	Consumer Goods (Children's Nightwear and Limited Daywear and Paper Patterns for Children's Nightwear) Safety Standard 2017	1	儿童睡衣裤套装
窒息/内灼伤危害	Button and coin batteries mandatory standards	2	带有LED灯的棒球帽（产品的纽扣电池幼儿易接触） 帽檐发光帽子（产品的纽扣电池幼儿易接触）
刺激皮肤和过敏反应危害	ACCC	1	哺乳枕

部分典型案例如下:


产品:	女式连帽夹克
原产国:	英国
通告国:	比利时
风险描述:	本产品含有过量的PFOA（测量值：34µg/kg）。这种物质具有致癌性，对环境有危害。
违反法规/标准:	POPs



产品:	塑料凉鞋
原产国:	中国
通告国:	马耳他
风险描述:	凉鞋的塑料材料含有过量浓度的邻苯二甲酸二（2-乙基己基）酯(DEHP)（测量值高达21.7%）和镉（测量值高达1.2 mg/kg）。DEHP可能会对生殖系统造成损害，从而损害健康。镉对人体健康有害，因为它在体内积累，会损害肾脏和骨骼，并可能导致癌症。
违反法规/标准:	REACH



产品:	儿童睡衣裤套装
原产国:	中国
通告国:	美国、加拿大
风险描述:	被召回的儿童睡衣违反了美国16 CFR 1615/1616儿童睡衣的易燃性法规，存在儿童烧伤的风险。 被召回的儿童睡衣违反了加拿大SOR/2016-169儿童睡衣的易燃性法规，存在儿童烧伤的风险。
违反法规/标准:	16 CFR 1615/1616、SOR/2016-169

中鼎检测技术有限公司

 E-mail: enquiry@cttlab.com <http://www.cttlab.com>
广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)

TEL: 0579-8998 6543

福建 (泉州、厦门)

TEL: 0595-6809 9099

香港

TEL: +852 9319 8131

越南 河内

 TEL: +84 024 3928 8688
E-mail: vn@cttlab.com

奥地利 林茨

 TEL: +43 670 1928192
E-mail: eu@cttlab.com

加拿大 温哥华

 TEL: +1 778 288 5623
E-mail: north.america@cttlab.com

 扫描左侧二维码，
关注“CTT 中鼎检测”
Scan QR code for
more information
V 2025.04



产品:	尿布套
原产国:	葡萄牙
通告国:	西班牙
风险描述:	该产品具有可以轻松拆卸的小部件(纽扣),小孩子可能会将它们放入口中吞咽并导致窒息。此外,在腰部有松散的装饰性蝴蝶结,这种具有自由末端的长绳可能会让儿童在各种活动中被困住,导致受伤。
违反法规/标准:	GPSR、EN 14682



产品:	青年夹克
原产国:	中国
通告国:	美国
风险描述:	该产品帽子区域的绳带可能会缠绕在某个物体上,会让儿童有绞勒受伤甚至致死的危险。这些夹克衫违反了美国联邦16 CFR 1120关于儿童上衣外套的法规,存在重大的产品危害。
违反法规/标准:	16 CFR 1120



产品:	肩包
原产国:	意大利
通告国:	法国
风险描述:	镍释放速率过高(测量值: 19 µg/cm ² /周)。镍是一种强致敏剂,如果存在于与皮肤直接和长时间接触的物品中,会引起过敏反应。
违反法规/标准:	REACH



产品:	儿童长裤
原产国:	土耳其
通告国:	比利时
风险描述:	该产品在腰部区域有带有自由末端的长功能绳带,这些绳带可能会让儿童在各种活动中被卡住,从而导致受伤。
违反法规/标准:	GPSR、EN 14682



产品:	童鞋
原产国:	中国
通告国:	法国
风险描述:	鞋头上的整个流苏和流苏上的织物/水钻元素很容易脱落,小孩子可能会把它们放进嘴里吞咽并导致窒息。
违反法规/标准:	GPSD

中鼎检测技术有限公司

 E-mail: enquiry@cttlab.com <http://www.cttlab.com>
广东 (东莞、深圳、惠州、广州、中山)
 TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)
 TEL: 0579-8998 6543

福建 (泉州、厦门)
 TEL: 0595-6809 9099

香港
 TEL: +852 9319 8131

越南 河内
 TEL: +84 024 3928 8688
 E-mail: vn@cttlab.com

奥地利 林茨
 TEL: +43 670 1928192
 E-mail: eu@cttlab.com

加拿大 温哥华
 TEL: +1 778 288 5623
 E-mail: north.america@cttlab.com




产品:	哺乳枕
原产国:	中国
通告国:	澳大利亚
风险描述:	涤纶长丝可能会从枕头的外壳中逸出。涤纶长丝有皮肤刺激和过敏反应的风险。
违反法规/标准:	ACCC



产品:	袜子
原产国:	土耳其
通告国:	爱尔兰
风险描述:	袜子里面的脚趾区域是用一个未剪断的环制成的，该环可能会导致脚趾区域紧绷，限制血液循环，从而导致受伤。
违反法规/标准:	GPSR



产品:	冬季室外玩耍保暖防水服
原产国:	越南
通告国:	加拿大
风险描述:	少量被召回的产品被发现含有霉菌。霉菌可能对免疫系统受损、肺部受损或对霉菌过敏的人构成健康风险。
违反法规/标准:	CCPSA



产品:	女式运动衫和男女款连帽衫
原产国:	秘鲁
通告国:	美国
风险描述:	召回的运动衫和连帽衫违反了美国联邦服装易燃性法规，对消费者构成烧伤危险。
违反法规/标准:	16 CFR 1610

各个市场对于纺织品及皮革鞋包类产品的要求不尽相同，因此，了解出口市场对产品的要求，尤其是儿童产品的要求，并严格按照相关法规和标准进行设计和生产则显得尤为重要，避免因产品质量问题而导致召回或产生索赔的风险。

参考网站:

<https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>
<https://www.cpsc.gov/Recalls>
<https://recalls-rappels.canada.ca/en/search/site>
<https://www.productsafety.gov.au/recalls>

备注：以上图片均来自以上参考网站。

中鼎检测技术有限公司

E-mail: enquiry@cttlab.com <http://www.cttlab.com>

广东 (东莞、深圳、惠州、广州、中山)

TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)

TEL: 0579-8998 6543

福建 (泉州、厦门)

TEL: 0595-6809 9099

香港

TEL: +852 9319 8131

越南 河内

TEL: +84 024 3928 8688
E-mail: vn@cttlab.com

奥地利 林茨

TEL: +43 670 1928192
E-mail: eu@cttlab.com

加拿大 温哥华

TEL: +1 778 288 5623
E-mail: north.america@cttlab.com



扫描左侧二维码，
关注“CTT 中鼎检测”
Scan QR code for
more information
V 2025.04